# Gallegos Canyon Unit

Tank treatment with 54GO 102 paraffin dispersant. 07/08/2015

## 1st Tank Thief

1st tank thief sample pulled before chemical treatment at 9:40 AM. Added a very small amount of 54GO directly to sludge/paraffin at 9:45 AM. Picture was taken at 10:05 AM





#### 1st Tank Thief







#### 1st Tank Thief







# 2<sup>nd</sup> Tank Thief

2nd tank thief pulled immediately after chemical injecting was completed. Picture was taken at 10:20 AM



2nd tank thief oil sample. Jar had just been knocked over on its side right before picture was taken at 10:31 AM



# 2<sup>nd</sup> Tank Thief

2nd tank thief oil sample. Picture was taken at 10:46 AM. Notice vertical striation in oil sample as water falls out of the oil.





2nd tank thief oil sample. Picture was taken at 11:16 AM. Notice vertical striations in oil sample as water falls out of the oil. Also notice the change in oil as the water continues to fall out as well as the BS&W falling to the bottom.



# 2<sup>nd</sup> Tank Thief

2nd Tank thief oil sample. Picture was taken at 11:30 AM.





# 3rd Tank Thief

3rd Tank thief taken at 10:35 AM and poured into jar at 10:39 AM





### 3rd Tank Thief







## 3rd Tank Thief





# 4th Tank Thief





# 4th Tank Thief





